


FUEL PUMPS

Mikuni Pulse Fuel Pumps employ an engine's fluctuating engine crankcase pressure to pump fuel from a remote fuel tank to the engine's carburetor.

TCI Part#	# Of Outlets	Style	Mounting	Flow Rate(litre/hr)
DF44-211 (non-asbestos)	1 (Single)	Rectangle	Flush	14
DF52-176 (non-asbestos)	2 (Dual)	Round	Bracket	35
DF52-73	2 (Dual)	Round	Flush	35
DF52-92	3 (Triple)	Round	Flush	35
DF52-136	2 (Dual)	Square	Flush	31
598-1883	2 (Dual)	Square	Flush	70
DF62-702	2 (Dual)	Pentagon	Flush	65




Single - Rectangular - Flush
DF44-211



Dual - Square - Flush
DF52-136



Dual - Round - Bracket
DF52-176



Dual - Hi Volume - Square - Flush
BRP 403-9012-00
598-1883



Dual - Round - Flush
DF52-73



Triple - Round - Flush
DF52-92



Dual - Pentagon - Flush
DF62-702



FUEL PUMP REBUILD KITS

Wafer Style Fuel Pump Rebuild Kits for DF44-211 Rectangular Fuel Pump

- A/C - 0636-272 / Bombardier - 403.8003.00 / Polaris - 3083115, 3083116, 3083117

Polymer pump material	SPI	598-1876
Polymer pump material	Winderosa 451449	598-1875

Round Single Style Fuel Pump Rebuild Kits for all OE Mikuni Single Outlet

Teflon pump material	Winderosa 451448	598-1873
Teflon pump material	SPI	598-1874

Round Double and Triple Style Fuel Pump Rebuild Kits for Mikuni DF-52 Double or Triple Fuel Pumps

Polymer pump material	SPI	598-1870
Teflon Pump Material	Mikuni MK-DF52	598-1878MK
Teflon Pump Material	Winderosa 451453	598-1879
Teflon Pump Material	SPI	598-1878

Rectangular Style Fuel Pump Rebuild Kits

Fits '74-78 Ski-Doo	Winderosa 462150	598-1866
---------------------	------------------	----------

Square Style Fuel Pump Rebuild Kits for Mikuni DF52-136 Fuel Pumps

- A/C 3636-640

Polymer pump material	Winderosa 451454	598-1871
Polymer pump material	SPI	598-1872

Pentagon Style Fuel Pump Rebuild Kits for Mikuni DF62-702 Fuel Pump

- Polaris 98-00 XCR 600/700/800, most 96-01 Domestic Twins
- A/C 87-00 ZRT 800 Thundercats and Mountincats

Polymer pump material	Winderosa 451457	598-1880
-----------------------	------------------	----------

Dual High Volume Square Fuel Pump Rebuild Kit

07-182

- Fits 598-1883 OEM 403-9012-00
- Ski Doo 1996 Mach 1 / 1997 Formula 583 / 1996 Formula SS, STX, STX LT / 1996-1997 Formula Z, MX 583, MX 670 / 1998-1999 Summit X 670 / 1999 MZX 670 HO, MZX 670 HO TH


Square Fuel Pump Rebuild Kit for Yamaha Rhino Fuel Pump

- Yamaha OEM 8FA-13910-00

Mikuni MK-DF52-531	598-0531
SPI	07-184



07-182




07-184




598-1866



598-1871



598-1873



598-1875



598-1879



598-1880

KEIHIN FUEL PUMP REBUILD KIT



Triangular Style Fuel Pump Rebuild Kit for Keihin

Fits Keihin fuel pump found on Yamaha (OE 8A5-24410-00-00, 8A5-24410-01-00, 8A5-24410-02-00, 8K4-24410-00-00)

- Made by Winderosa Part #451420

Polymer pump material

598-1877

CARBURETOR REBUILD KITS - PWC

Mikuni BN Round Pump Rebuild Kit

- Carburetor kit for diaphragm pump-type carburetors found on Personal Watercrafts.
- For BN34, BN38 & BN44 Round Pump Carburetors found on early Yamaha, Kawasaki Personal Watercrafts with round style pump chamber.

Made by Mikuni MK-BN38/44

Made by Winderosa Part#462140 598-1400

Mikuni BN Square Pump SPR Rebuild Kit

- Fits Mikuni Super BN carburetors 34 mm, 38 mm, 44 mm, and 46 mm

Made by Mikuni MK-BN38/44 SPR

Made by Winderosa Part# 451460 598-1460

Mikuni Super BNi Rebuild Kit

- Fits Mikuni Super BNi carburetors

Made by Mikuni MK-BN46i

Made by Winderosa Part# 451469 598-1469

CARBURETOR REBUILD KITS - ATV

ATV Carburetor Repair Kits

Complete kits to rebuild O.E. carburetors. Each kit contains all necessary gaskets, o-rings, float valve and jets.

* repair kit designed for 2 carburetors

Model	Year	TCI #
HONDA		
TRX 90	99-08	598-3047
TRX 250X	87-88 / 91-92	598-3020
TRX 300EX	93-08	598-3038
TRX 400FA / TRX 400FGA	04-07	598-3045
TRX 450ER / TRX 450R	06-09	598-3050
TRX 450R	04-05	598-3049
TRX 500FA / TRX 500FGA	01-04	598-3043
TRX 650FA / TRX 650FGA	03-05	598-3046
POLARIS		
Trail Blazer	96-00	598-3405
Xplorer 4x4	2000	598-3405
SUZUKI		
LT 250R	88-92	598-3218

Model	Year	TCI #
KAWASAKI		
KVF 360	03-09	598-3112
KLF 400	96-99	598-3108
KSF 400	03-06	598-3221
KVF 400	99-02	598-3110
KVF 650	02-09	598-3113 *
KSV 700	04-09	598-3116 *
KVF 700	04-06	598-3113 *
YAMAHA		
YFM 350R	04-08	598-3322
YFM 350 / 4WD	04-09	598-3321
YFZ 350	88-06	598-3308
Big Bear 400	00-12	598-3312